

Specialty Ring Products Excess Bar Stock

Part	Heat Number	On Hand Qty (Lbs.)	Mill
M50 NIL-3.00	V00137-K01 (MS-229B)	492	UNIVERSAL
M50 NIL-4.00	V02488K02	306	UNIVERSAL
M50 NIL-4.00	V02620K02	317	Universal
M50 NIL-6.00	E9177-3	232	LATROBE
VAR 4340-6.00	J2487-1	17	LATROBE
VAR 4340-7.00	J4974-3	382	LATROBE
VAR 52100-2.00	D7757-5	72	LATROBE
VAR 52100-2.00	J4606-8	372	LATROBE
VAR M50-2.50	J3860-8	187	LATROBE
VIMVAR 52100-2.00	A2075-1	465	LATROBE
VIMVAR 52100-3.00	E9508-3	374	LATROBE
VIMVAR 52100-3.00	E9545-5	888	LATROBE
VIMVAR 52100-3.50	E9347-2	600	LATROBE
VIMVAR M50-5.00	V03400K01	761	UNIVERSAL
VIMVAR M50-7.00	V02912K01	1275	UNIVERSAL

Part	Heat Number	On Hand Qty	Mill
M50 NIL-5.00	E9285-5	211	LATROBE
M50 NIL-5.00	A4000-6	205	LATROBE
M50 NIL-5.00	E9645-3	311	LATROBE
M50 NIL-5.00	E9645-5	400	LATROBE
M50 NIL-5.00	E9645-6	315	LATROBE
M50 NIL-5.00	A4229-4	262	LATROBE
M50 NIL-5.00	E9624-4	239	LATROBE
M50 NIL-5.00	A4451-7	275	LATROBE
M50 NIL-5.00	A4451-5	356	LATROBE
M50 NIL-5.00	E9788-4	194	LATROBE
M50 NIL-5.00	E9766-7	261	LATROBE
M50 NIL-5.00	E9791-3	172	LATROBE
M50 NIL-5.00	E9742-6	211	LATROBE
M50 NIL-5.00	E9766-4	132	LATROBE
M50 NIL-5.00	E9840-3	367	LATROBE
M50 NIL-5.00	E9860-3	141	LATROBE
M50 NIL-5.00	E9860-2	250	LATROBE
M50 NIL-5.00	E9903-2	172	LATROBE
M50 NIL-5.00	E9958-6	217	LATROBE
M50 NIL-5.00	G0194-1	171	LATROBE
M50 NIL-5.00	G0194-3	227	LATROBE
M50 NIL-5.00	G0217-4	211	LATROBE
M50 NIL-5.00	G0259-7	222	LATROBE

AMS-6308

Part	Heat Number	On Hand Qty	Mill
EX 53-3.25	A1516-5	133	LATROBE
EX 53-3.25	A2239-3	1189	LATROBE
EX 53-3.25	E8364-5	682	LATROBE

Specialty Ring Products Excess Bar Stock

EX 53-3.25	E8280-5	1358	LATROBE
EX 53-4.50	E9713-7	225	LATROBE

Part	Heat Number	On Hand Qty	Mill
VAR 9310-5.00	G28552-K07	305	UNIVERSAL
VAR 9310-5.00	J7438-3	367	LATROBE
VAR 9310-5.00	J7310-2	2542	LATROBE
VAR 9310-5.00	J7494-1	3230	LATROBE
VAR 9310-5.00	J7438-2	4816	LATROBE
VAR 9310-5.00	951718-3	1740	CARPENTER
VAR 9310-5.00	951785-1	11180	CARPENTER
VAR 9310-5.00	J8248-2	4292	LATROBE
VAR 9310-5.00	J8248-1	7678	LATROBE
VAR 9310-5.00	J7867-3	373	LATROBE
VAR 9310-5.00	J8311-2	4820	LATROBE
VAR 9310-5.00	J8311-3	9662	LATROBE
VAR 9310-5.00	J8545-3	4484	LATROBE
VAR 9310-5.00	J8390-3	4590	LATROBE
VAR 9310-5.00	J8650-1	3588	LATROBE
VAR 9310-5.00	J8591-3	1546	LATROBE
VAR 9310-5.00	951977-3	2101	CARPENTER

Part	Heat Number	On Hand Qty	Mill
VAR 52100-4.00	J8115-5	1910	LATROBE
VAR 52100-4.00	J8115-6	2348	LATROBE
VAR 52100-4.00	J8115-2	2328	LATROBE
VAR 52100-4.00	J8394-3	4584	LATROBE
VAR 52100-4.00	J8394-8	2514	LATROBE
VAR 52100-4.00	J8608-5	1758	LATROBE
VAR 52100-4.00	J9236-1	5876	LATROBE